

### **Business Case for Decarbonization**



Utility cost savings, avoided carbon tax, and capital project planning can provide positive NPV



Tenant attraction and retention




Revitalization and repositioning can create value from benefits beyond energy and carbon



Futureproofing, long-term value, and reduced transition risk

https://www.mckinsey.com/industries/real-estate/our-insights/climate-risk-and-the-opportunity-for-real-estate

**DIALOG** 



Minimum National Carbon Pollution Price (\$/tonne)

Cost of carbon will continue to increase for Canada to meet it's climate change goals

Source: Update to the Pan-Canadian Approach to Carbon Pollution Pricing 2022-2030 - Canada ca

# **Mitigating Policy Risk**




Major municipalities across Canada are planning to implement emissions limits for existing buildings

**DIALOG** 

5

# **Approaches to Asset Decarbonization**




### Business as Usual / Baseline

- Lifecycle replacement and opportunistic upgrades
- As-needed / quickpayback projects
- Very unlikely to get to zero




#### Zero Carbon over Time (ZCoT)

- Requires long term planning
- Gradual investment, gradual results
- Small/large projects
- Pathway to zero emissions



# Deep Green Retrofit and Repositioning

- Requires deep technical and financial analysis
- High investment, quick results
- One large implementation
- Instant impact




creates opportunities for

 placemaking and deeper community impact

DIALOG

# **Public Sector Precedents**



7

# **HSBC Place - Deep Energy Retrofit** (2017)

- Approx. 318,000 sq. ft., 18-storey commercial office building
- Located in downtown Edmonton, AB
- Originally constructed in 1980



Well-located building with long service life



Requires major capital expenditure



Tenant or occupant turnover is imminent




Potential for revitalization and repositioning





DIALOG




### **Building Envelope - Before**

- Double-pane insulated glass in curtain wall with aluminum frames
- 300 reported window seal failures indicates end of life
- Operations report systemic leaks in the curtain wall and condensation in the winter
- Thermal performance very poor



**DIALOG** 



Building Envelope - After

PRESSURE PLATE AND CAP
Triple Glazed + 2x Low E + Argon

New lower window sill

New 9'-0" window head

Window shades to integrate into ceiling

Extended options for exterior design

DIALOG'

### **Mechanical - Before**

- Heating: 3 x natural gas-fired boilers, 36 years old, ~80% efficient
- Cooling: 2 x centrifugal chillers, roof-mounted cooling towers
- 2-zone VAV supply air from penthouse fans, split north/south, no heat recovery
- · Perimeter radiation





DIALOG.

13

## **Mechanical Upgrades**



New Fan Coil System

- Increased number of zones
- All services located in the ceiling (no baseboards)



Dedicated outdoor air system (DOAS) equipped with enthalpy wheel heat recovery and DCV controls




Variable Primary Pumping



Heating: Condensing boilers with low temperature heating design




Cooling: High-efficiency magnetic bearing chillers



**DIALOG®** 

# **Data Centre Free Cooling**



Three modes of cooling:

- 1. Mechanical cooling (WBT >10C) all cooling by chillers only
- 2. Hybrid cooling ( 0 < WBT < 10C)
   cooling provided by chillers
  with waterside economizer as
  first stage
- 3. Free cooling mode (WBT < 0C) cooling provided by evaporative cooling only

**DIALOG** 

15

# **Lighting - Before**

- · 347V fluorescent lighting
- ON/OFF relay lighting controls
- No centralized controls



**DIALOG** 


# **Lighting - After**


- All LED luminaires
- Individual control via digitally addressable lighting interface (DALI)
- Daylight harvesting and occupancy-based controls
- New equipment extends electrical distribution life by 30-40 years




**DIALOG** 


17




























- LEED Gold Certified
- WELL Gold Certified
- WiredScore Platinum
- 100 bicycle storage spaces with showers, lockers, repair station
- 13 electric vehicle chargers
- Full-service fitness and wellness centre

**DIALOG** 

